APPENDIX B-PHOTOGRAPHS

CES Environmental and Social Advisory Services



Figure 1:View of general surroundings in the project area.



Figure 2:Flat, sandy to gravelly terrain within the Soutrivier South project area on Farm RE/195.

2



Figure 3: Typical rocky dolerite outcrop and vegetation observed.



Figure 4: Typical alluvial area with standing water and sparse vegetation.

3

CES Environmental and Social Advisory Services



Figure 5: Typical transformed area associated with a dwelling and an unpaved gravel road